

FOCTT2 Firmware Update Tool for macOS v1.0.9

Contents

General	2
Supported Hardware.....	2
Supported OS Compatibility	2
Tested OS Compatibility	2
Released Production Files.....	2
Product Upgrade	2
New Features.....	3
New Features added in version 1.0.9	3
Resolved Issues	4
Issues resolved by version 1.0.9	4
Outstanding Issues.....	5
New Issues	5
Existing Issues.....	5
Document History	6

Copyright © 2020 Panduit Corp. All rights reserved. No part of this book shall be reproduced, stored in a retrieval system, or transmitted by any means, electronic, mechanical, photocopying, recording or otherwise, without written permission from Panduit. No patent liability is assumed with respect to the use of the information contained herein.

Although every precaution has been taken in the preparation of this book, Panduit assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of the information contained herein.

General

V1.0.9 is a GENERAL RELEASE of the OCTT2 Firmware Update Tool.

Supported Hardware

<i>Model</i>	<i>Required Firmware to support Release</i>	<i>Notes</i>
OCTT2	Boot loader v2.03 and newer Firmware v1.0.3 and newer	FOCTT2_FWUP_Mac v1.0.9 includes firmware v1.1.1.

Supported OS Compatibility

<i>Application</i>	<i>Support</i>	<i>Known Limitations</i>
Mac OS X 10.9.5 and newer	Yes	We expect this software to work correctly on all versions of MacOS X 10.9.5 or newer. If you encounter an issue, please see "Troubleshooting: Support."

Tested OS Compatibility

<i>Application</i>	<i>Support</i>	<i>Known Limitations</i>
Mac OS X Mavericks	v10.9.5	
macOS El Capitan	v10.11.5	
macOS High Sierra	v10.13.4	
macOS Monterey	v12.6.3	

Released Production Files

Product Upgrade

Image Information

Filename: FOCTT2_FWUP_Mac_1_0_9.dmg

Filesize: 4446531 bytes

CRC32: 8AA3D7EF

MD5: d2b1c275e57bd5f86e2802c5695a6c22

SHA1: c53cd822bdba40adf6a43722fb245f27569142aa

SHA256: 7366de9c1a29beef6d6a4f5f398b0c1e0ec66332479d9b6e6a13219c115d693d

SHA512:

b071146f91b4eec9c66112caceae1193e2fbf4f64a03a3944b09a30fa8bb5c2e4588723c25d89

a20056709bb666a22ab8591473056761f8b175d53d38e6cf7d4

RIPEMD160: 12931f6de9c3f4b5b2b88f9a21f35fb7175a60ea

New Features

New Features added in version 1.0.9

<i>Issue ID</i>	<i>Title</i>
OC-332	The firmware loader provides firmware v1.2.1.
OC-351	The firmware loader provides firmware v1.3.3.

Resolved Issues

Issues resolved by version 1.0.9

<i>Issue ID</i>	<i>Title</i>
	N/A

Outstanding Issues

New Issues

The following reported problems have been found since the previous release and are still outstanding in this release.

<i>Issue ID</i>	<i>Title</i>	<i>Version</i>	<i>Status</i>
	N/A		

Existing Issues

The following reported problems were found prior to the previous release and are still outstanding.

<i>Issue ID</i>	<i>Title</i>	<i>Version</i>	<i>Status</i>
OCBgz115	When updating a tool from 1.0.3 to 1.0.6, the word "Complete" did not propagate correctly.	BL2.03	Fixed in BL2.04

OCBgz115 Sometimes the status reported by Bootloader v2.03 is not accurate when the firmware update has failed or when it has completed successfully.

Workaround: If other USB devices are attached to the computer, remove them. If no other USB devices are attached to the computer, then attach another USB device, or plug the OptiCam2 into a different USB port, or plug the OptiCam2 into a USB hub. Retry the firmware update procedure until the OptiCam2 LCD screen shows the updated firmware version at the top of the "... "Select Option" screen.

Document History

Revision	Date	Reason for Change
1	Sep 29, 2022	Include firmware 1.2.1.
2	Aug 25, 2023	Rebuild to include firmware 1.3.3.