

smartzone™ **mPower**

Software Release Notes 1.0.2

Contents

- General 3
 - Tested Application Compatibility..... 3
 - Released Production Files 3
 - Product Upgrade 3
 - Upgrade..... 3
- New Features..... 4
 - New Features added in version 1.0.2 4
- Outstanding Issues..... 5
 - New Issues 5
- Release History 7



General

Tested Application Compatibility

<i>Application</i>	<i>Support</i>	<i>Known Limitations</i>
SmartZone UPS Network Management Card	V1.1.2	Does not include 3-Phase UPS in power average.

Released Production Files

Product Upgrade

Image Information

Filename: mPowerSetup.exe

Version: 1.0.2

CRC32: 702542CE

SHA256: 7417a80ce3c397eef935cfee1edb86a5a76158a76541413a9f1fdb32307d1fa6

File size: 27704952 bytes

Upgrade

This is the initial release of *mPower* so there is no upgrade needed. If a reinstall of *mPower* is needed, it must first be uninstalled through “Add or Remove Programs”.

New Features

New Features added in version 1.0.2

The initial release provides:

- Dashboard Monitoring
 - Alarm and Event Log Aggregation
 - Bulk Firmware Update
 - Bulk Configuration Update
-

Outstanding Issues

New Issues

The following reported problems have been found and are still outstanding in this release.

<i>Issue ID</i>	<i>Title</i>	<i>Version</i>	<i>Status</i>
MPOW-122	<i>mPower HTTPS server is affected by CVE-2022-0778</i>	1.0.2	Deferred
MPOW-120	<i>Range checking is missing from some mPower settings</i>	1.0.2	Deferred
MPOW-115	<i>mPower does not reinstall properly</i>	1.0.2	Deferred
MPOW-17	<i>Power data is not included from 3-Phase UPSes</i>	1.0.2	Deferred
MPOW-86	<i>mPower repeats automatic logout messages</i>	1.0.2	Deferred

MPOW-122 *mPower* HTTPS server is affected by CVE-2022-0778

This may prevent *mPower* from updating data from managed devices.

Workaround: None

MPOW-120 Range checking is missing from some *mPower* settings

Some settings may be entered as text instead of numbers, this will cause the function to misoperate.

Workaround: None

MPOW-115 *mPower* does not reinstall properly

If the *mPower* service is already running and the installer is run again, the installer is unable to replace the existing executable.

Workaround: Uninstall *mPower* before reinstalling

MPOW-17 Power data is not included from 3-Phase UPSes

If *mPower* is connected to 3-Phase UPSes, it does not properly average the phase power output. The result is the Dashboard average power output is only for 1-Phase UPSes.

Workaround: None

MPOW-86 *mPower* repeats automatic logout messages

When the browser is closed without logging out from *mPower*, *mPower* will automatically close the session upon the set timeout. It will then repeat the session timeout message every hour.

Workaround: Logout before closing *mPower*

Release History

Revision	Date	Reason for Change
1.0.2	March 31, 2022	Initial Release