

VeriSafe 2.0 Isolation Module Firmware Revision Notice

VeriSafe Finished Good Models: VS2-AVT-1PB-02, VS2-AVT-1PB-08, VS2-AVT-1PB-16, VS2-AVT-1PF-02, VS2-AVT-1PF-08, VS2-AVT-1PF-16, VS2-AVT-3PB-02, VS2-AVT-3PB-08, VS2-AVT-3PB-16, VS2-AVT-3PF-02, VS2-AVT-3PF-08, VS2-AVT-3PF-16

VeriSafe Isolation Module Models: VS2-AVT-3P-ISO, VS2-AVT-1P-ISO

Firmware Version: 2.0.0

Date: 6/30/2023

Author: Alan Bond

Description of Changes

NOTE: This firmware is not required for continued functionality of installed VeriSafe AVT systems without the Network Module. This firmware is only required to unlock features utilized by the Network Module.

NOTE2: The firmwares of the VeriSafe 2.0 Isolation Module and Network Modules must be 2.0.0 or later. The appropriate firmwares are packaged together in the below download.

NOTE3: A VeriSafe 2.0 Network Module (VS2-NET) is required to update the Isolation Module firmware.

The VeriSafe 2.0 AVT firmware revision 2.0.0 unlocks some exciting new features and improvements when paired with the VeriSafe 2.0 Network Module! See list below.

- Addition of Remote Activation communication from Network Module
- Improved voltage reporting accuracy for DC systems
- Addition of live temperature reading of the Isolation Module. (NOTE that this is NOT ambient)
- Improved AC/DC auto detection to better identify DC systems with AC noise present

Download the VeriSafe 2.0 AVT here: [Firmware Revision 2.0.0](#)

Many other downloads are available here: [Software, Firmware, Printers on Panduit.com](#)

For any questions or concerns, please reach out to Panduit Technical Support:

Email: techsupport@panduit.com

Tel: 1-866-405-6654