

VeriSafe 2.0 Network Module Firmware Revision Notice

VeriSafe Models: VS2-NET

Firmware Version: 2.0.1

Date: 6/30/2023

Author: Alan Bond

Description of Changes

NOTE1: A VeriSafe 2.0 Isolation Module is required to utilize the functionality of the VeriSafe 2.0 Network Module.

NOTE2: The firmwares of VeriSafe 2.0 Isolation Module and Network Modules must be 2.0.0 or later. The appropriate firmwares are packaged together in the below download.

The VeriSafe 2.0 Network Module firmware revision 2.0.1 unlocks some exciting new features and improvements to your VeriSafe 2.0 AVT system! See list below.

- Addition of Remote Activation via web interface, EtherNet/IP and Modbus TCP protocols
- Addition of live temperature reading of the Isolation Module, viewable via the web interface, EtherNet/IP and Modbus TCP protocols. (NOTE that this is NOT ambient)
- Improved voltage accuracy reporting below 50V with new power system configuration options
- Changed default web server mode to HTTPS
- Addressed security vulnerabilities identified by WebInspect
- Added open-source license acknowledgments
- Updated data log formatting
- Updated information provided on “Support” page

Download the VeriSafe 2.0 Network Module here: [Firmware Revision 2.0.1](#)

Many other downloads are available here: [Software, Firmware, Printers on Panduit.com](#)

For any questions or concerns, please reach out to Panduit Technical Support:

Email: techsupport@panduit.com

Tel: 1-866-405-6654