

## Configuration

Panduit MP300 Printer firmware release version AAAA

### Firmware Version 1710

Notes:

1. This is the control drawing for the MP300 firmware.
2. The source files for the latest version of the MP300 firmware are built and compiled by external supplier (Seiko Epson Corp.). The executable file is stored and controlled by the BitBucket Management Software.
3. The distribution firmware file for MP300 firmware consists of one Windows executable file. This executable file contains both updater application and the firmware image. The following table describes the firmware version being released as part of the ECN transaction.

f/w sub products	Product	f/w version
Firmware updater	EXT	<a href="#">1710</a>

f/w Product	Target MCU	H/W PCB Version	Programming method
EXT	N/A	N/A	PC executable with USB

4. The high-level firmware update sub product (executable file) is provided by external supplier. It shall be used to update the MP300 printer firmware.

1) EXT: UpdaterMP300\_V1710.exe

File Name	Product	MD-5
<a href="#">UpdaterMP300_V1710.exe</a>	Exe	4A264223503254789C7DC9B148499D8F

## SOFTWARE SECTION

5. This firmware updater merged the software application and firmware image file into one executable file

# 1003658

# MP300 FIRMWARE

## REVISION HISTORY

REV	DATE	BY	CHK	DESCRIPTION	ECN	CUST	SUP
AE	4/4/22	MBRA JSUN	MSDA	<a href="#">1500 Release Notes</a>	078211/04	BRJO	MEL
AF	10/27/22	RYKA	MBRA	<a href="#">1600 Release Notes</a>	078211/05	BRJO	GSI
AG	12/01/23	JERP	RYKA	<a href="#">1700 Release Notes</a>	078211/06	BRJO	SBAS
AH	12/01/23	MBRA	JSUN	<a href="#">1710 Release Notes</a>	078211/07	BRJO	SBAS